

# **City of Wichita, Kansas Americans with Disabilities Act Transition Plan**

## **City Hall**

455 N. Main

**August 2005**



Prepared by

**DMCG**

**Disability Management Consulting Group L.L.C.**

2801 Jonquil Place

Columbia, MO 65202

In conjunction with

**The Great Plains ADA & IT Center and the City of Wichita Disability Advisory Board**

---

**Index**

<b>Parking Garage -</b>	<b>3</b>
<b>Basement Level -</b>	<b>4</b>
<b>First Floor -</b>	<b>5</b>
<b>Second Floor -</b>	<b>7</b>
<b>Third Floor –</b>	<b>9</b>
<b>Fourth Floor –</b>	<b>13</b>
<b>Fifth Floor –</b>	<b>15</b>
<b>Sixth Floor –</b>	<b>17</b>
<b>Seventh Floor –</b>	<b>18</b>
<b>Floor Eight –</b>	<b>19</b>
<b>Floor Nine –</b>	<b>22</b>
<b>Floor Ten –</b>	<b>24</b>
<b>Floor Eleven –</b>	<b>27</b>
<b>Floor Twelve –</b>	<b>29</b>
<b>Floor Thirteen -</b>	<b>31</b>

[illegible]

[illegible]

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
8. Ground Floor	The counter, at the City Hall Express, is located too high measuring 40-inches.	<a href="#">7.2</a>	ADAAG requires a minimum 36-inch long portion of sales or service counters to be a maximum height of 36-inches. <b>Lower a portion of the existing counter to a maximum height of 36-inches.</b>	M	H	M	<a href="#">1</a>	\$200	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			
9. Ground Floor	The paper vending machines, in the lobby, do not provide appropriate clear ground space.	<a href="#">4.25.3</a>	Where accessible operating mechanisms or devices are available to the general public, a clear floor or ground space at least 30 in by 48 in (760 mm by 1220 mm) that allows either a forward or parallel approach by a person using a wheelchair shall be provided. Appropriate clear floor space does not exist at the paper vending machines due to a narrow hallway. <b>Relocate the vending machines so that appropriate clear floor space exists.</b>	H	H	M	<a href="#">1</a> <a href="#">4</a>	\$0	<a href="#">ADAAG</a>			
10. Ground Floor	The path of travel, leading to the seating area in the Council Chambers, has a very steep running slope.	<a href="#">4.8</a>	At least one accessible path of travel is required to lead to all accessible rooms and spaces. The slope of the existing ramp is steeper than ADAAG's maximum of 8.33%. The existing ramp measures over 12%. <b>Modify the ramp to comply with ADAAG specifications, or otherwise ensure an accessible path of travel exist leading to all required accessible spaces in the seating area.</b>	H H ®	H	M	<a href="#">1</a> <a href="#">0</a>	\$1,000	<a href="#">Ramp Detail</a>			
11. Ground Floor	Appropriate maneuvering clearance does not exist at the entrance door to the Council Chambers	<a href="#">4.13.6</a>	The existing entrance door provides 8-inches of space at the latch pull side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify this door to comply with ADAAG specifications, or otherwise ensure that an appropriate number of fully accessible entrances lead to the Council Chambers.</b>	M	H	M	<a href="#">1</a> <a href="#">3</a>	\$500	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			
12. Ground Floor	It is not known if an assistive listening system or assistive listening devices are available for individuals who are hard or hearing in the Council Chambers.	<a href="#">4.1.3(19(b))</a>  <a href="#">4.33.6</a>	ADAAG requires an assistive listening system to be available either to serve a specific seating area or so that the system can be utilized at any seat in the auditorium. ADAAG also requires that signage be posted notifying patrons that such assistive listening devices are available. <b>Ensure that an appropriate number of assistive listening devices are available upon request and that appropriate signage is posted at the information desk.</b> See <a href="#">ADAAG</a> for more information.	H H	H	M	N A	\$2,000	<a href="#">ADAAG</a>			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations	Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
13. Ground Floor - Restrooms	The coat hooks, in both the men’s and women’s restrooms, are located too high.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>	L	H	M	<a href="#">4</a>	\$20	<a href="#">Building Block 10 – Reach Ranges</a>			
14. Ground Floor - Restrooms	The toilet’s, in the accessible stalls of the men’s and women’s restrooms, are centered at 19.5-inches.	<a href="#">4.16</a>	According to ADAAG, accessible water closets must be centered at 18-inches from the side wall. <b>Move the water closets so are centered at 18-inches.</b>	L	H	M	<a href="#">3</a>	\$1,000	<a href="#">Restroom Figures – Building Blocks</a>			
15. Ground Floor - Restrooms	Urinals, in the men’s restroom, are located too high.	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	<a href="#">2</a>	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
16. Ground Floor - Restrooms	The accessible toilet stall, in the men’s restroom, is inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall and lack of rear grab bar. <b>Modify the restroom to comply with ADAAG specifications, if it is technically feasible to do so.</b>	H	H	M	<a href="#">3</a>	\$3,000	<a href="#">Restroom Figures – Building Blocks</a>			
17. Ground Floor - Restrooms	The seat cover dispensers, in the women’s restroom, are located too high at 62-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser to meet ADAAG reach range specifications.</b>	M	H	M	<a href="#">5</a>	\$50	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3</a> .			

[illegible]



**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access		Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)		
22. Second Floor	The faucet control, on the drinking fountain, does not comply with ADAAG specifications.	<a href="#">4.15</a> <a href="#">4.1.3(10)</a>	Controls and operating mechanisms on accessible drinking fountains are required to be operable with one hand and not require tight grasping, pinching, or twisting of the wrist. Push button or lever type faucet controls will comply with this specification. <b>Replace faucet control on the existing fountain or replace the fountain with one that has compliant faucet controls.</b>	L	H	M	<a href="#">27</a>	\$300	<a href="#">Building Block 7 – Drinking Fountains</a>					
23. Second Floor	In the Cafeteria, the Cereal shelf is located too high at 64-inches.	<a href="#">5.6</a>	According to ADAAG, self-service shelves and dispensing devices for tableware, dishware, condiments, food and beverages shall be installed to comply with reach ranges specified in <a href="#">4.2</a> (see <a href="#">Fig. 54</a> ). <b>Lower the existing shelf or provide a second set of items located on this shelf on a lower accessible shelf.</b>	H	H	M	<a href="#">29</a>	\$20	<a href="#">ADAAG</a>					
23. Second Floor - Restrooms	The seat cover dispensers, in the women’s restroom, are located too high at 62-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser to meet ADAAG reach range specifications.</b>	M	H	M	N A	\$50	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3</a> .					
24. Second Floor - Restrooms	Urinals, in the men’s restroom, are located too high.	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	<a href="#">25</a>	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.					
25. Second Floor - Restrooms	An accessible stall does not exist in the men’s or women’s restrooms due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall and lack of rear grab bar. <b>Modify the restroom to comply with ADAAG specifications, if it is technically feasible to do so.</b>	H	H	M	<a href="#">26</a>	\$6,000	<a href="#">Restroom Figures – Building Blocks</a>					



[illegible]

[illegible]

[illegible]

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
34. Third Floor	The Witness Stands, located in Courtrooms B and A, are inaccessible due to steps and do not provide appropriate maneuvering space.		Witness stands are required to be located on an accessible path of travel and provide unobstructed turning space complying with <a href="#">4.2.3</a> . <b>Ensure that the witness stands, in each courtroom, are on an accessible path of travel and provide appropriate maneuvering space; or otherwise ensure that the Courts program is fully accessible when necessary regarding a person with a disability.</b>	H	M	M	<a href="#">1</a> <a href="#">7</a>	\$2,000	See <a href="#">Proposed Final Rule - Judicial, Legislative, and Regulatory Facilities</a>			
35. Third Floor	A hi-lo drinking fountain does not exist on this level.	<a href="#">4.15</a> <a href="#">4.1.3(10(a))</a>	Cups at inaccessible drinking fountains are considered equivalent facilitation. <b>Provide a cup holder at the existing drinking fountain.</b>	L	L	M	<a href="#">1</a> <a href="#">9</a>	\$25	<a href="#">ADA TAM 3 – P 34</a>			
36. Third Floor	The faucet hardware, on the existing drinking fountain, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b>	L	L	M	<a href="#">1</a> <a href="#">9</a>	\$150	<a href="#">ADAAG Building Block 7 – Drinking Fountains</a>			
37. Third Floor - Restrooms	The coat hooks, in both the men's and women's restrooms, are located too high at 65-inches.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>	L	H	M	<a href="#">2</a> <a href="#">6</a>	\$20	<a href="#">Building Block 10 – Reach Ranges</a>			
38. Third Floor - Restrooms	The seat cover dispensers, in the men's and women's restrooms, are located too high at 62-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser, in each restroom, to meet ADAAG reach range specifications.</b>	M	H	M	<a href="#">2</a> <a href="#">8</a> <a href="#">3</a> <a href="#">2</a>	\$100	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3</a> .			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations	Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
39. Third Floor - Restrooms	The toilet stalls, in the men’s and women’s restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall and lack of rear grab bars, toilets not centered at 18-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b>	M	H	M	<a href="#">2636</a>	\$3,000	<a href="#">Restroom Figures – Building Blocks</a>			
40. Third Floor - Restrooms	Appropriate maneuvering clearance does not exist at the entrance doors to the men’s and women’s restrooms.	<a href="#">4.13.6</a>	The existing entrance doors provide 4-inches of space at the latch pull side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify the doors to comply with ADAAG specifications.</b>	M	H	M	<a href="#">3033</a>	\$1,000	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			
41. Third Floor - Restrooms	Urinals, in the men’s restroom, are located too high.	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	<a href="#">34</a>	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
42. Fourth Floor	The Support Services entrance door does not provide appropriate opening hardware.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify this door by replacing door knobs with lever-type hardware or installing add-on levers.</b>	H	H	M	<a href="#">33</a>	\$150	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
43. Fourth Floor	The writing counter in the in the Credit Union room is located too high at 40-inches. .	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that a desk in close proximity to the counter is available and can be utilized when necessary.</b>	H	H	M	<a href="#">35</a>	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
44. Fourth Floor	The teller counter in the Credit Union room is located too high at 41-inches.	<a href="#">7.2</a>	ADAAG requires a minimum 36-inch long portion of sales or service counters to be a maximum height of 36-inches. <b>Lower at least one of the existing teller counters to a maximum height of 36-inches.</b>	M	H	M	36	\$200	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			
45. Fourth Floor	Appropriate maneuvering clearance does not exist at the entrance door to the Special Investigations room.	<a href="#">4.13.6</a>	The existing entrance doors provide 11-inches of space at the latch pull side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify the door to comply with ADAAG specifications.</b>	M	H	M	39	\$1,000	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			
46. Fourth Floor	The public counter in the Special Investigations room is located too high at 48-inches.	<a href="#">7.2</a>	ADAAG requires a minimum 36-inch long portion of sales or service counters to be a maximum height of 36-inches. <b>Lower a minimum 36-inch long section or the existing counter to a maximum height of 36-inches.</b>	M	H	M	38	\$200	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			
47. Fourth Floor - Restrooms	The toilet stalls, in the men's and women's restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall and lack of rear grab bars, toilets not centered at 18-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b>	M	H	M	42	\$3,000	<a href="#">Restroom Figures – Building Blocks</a>			
48. Fourth Floor - Restrooms	The coat hooks, in both the men's and women's restrooms, are located too high at 65-inches.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>	L	H	M	41	\$20	<a href="#">Building Block 10 – Reach Ranges</a>			



**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
49. Fourth Floor - Restrooms	The seat cover dispensers, in the women's restroom, are located too high at 62-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.2.4</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser to meet ADAAG reach range specifications.</b>	M	H	M	N A	\$50	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3</a> .			
50. Fourth Floor - Restrooms	Urinals, in the men's restroom, are located too high.	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	N A	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
51. Fifth Floor	Round door hardware exists on the entrance door and throughout the interior of the Professional Standards Office.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing door knobs with lever-type hardware or installing add-on levers.</b>	L	H	M	4 5	\$200	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
52. Fifth Floor	The counter in the Field Services Office is located too high at 42-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that a desk in close proximity to the counter is available and can be utilized when necessary.</b>	H	H	M	4 8	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			
53. Fifth Floor	The counter in the Records Office is located too high at 42-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that a desk in close proximity to the counter is available and can be utilized when necessary.</b>	H	H	M	5 0	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			



[illegible]

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
58. Sixth Floor	Round door hardware exists on the entrance door to the interview room in the Lab.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.</b>	L	H	M	60	\$25	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
59. Sixth Floor	The counter, in the Investigations Department, is located too high at 42-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	63	\$0	<a href="#">ADAAG</a> <a href="#">New ADAAG</a>			
60. Sixth Floor	The faucet hardware, on the existing drinking fountain, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b>	L	L	M	NA	\$150	<a href="#">ADAAG</a> <a href="#">Building Block 7 – Drinking Fountains</a>			
61. Sixth Floor - Restrooms	The accessible toilet stalls, in the men's and women's restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall, lack of rear grab bars, toilets not centered at 18-inches, toilet seats too high at 20-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every restroom may not need to be made fully accessible, so long as restrooms services, as a whole, are accessible and usable by patrons with disabilities. Therefore, this restroom may not need to be made fully accessible so long as other fully accessible restrooms are fully accessible and in close proximity to inaccessible restrooms.	M	H	M	66 68	\$5,000	<a href="#">Restroom Figures – Building Blocks</a>			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access		Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions				
Location		Identified Issue		ADAAG Specifications		Recommended Correction		Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
62. Sixth Floor - Restrooms		The coat hooks, in the men’s, restroom, is located too high at 66-inches.		4.25.3		Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG 4.2.5 or 4.2.6. Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.		L	H	M	N A	\$20	Building Block 10 – Reach Ranges			
63. Sixth Floor - Restrooms		Urinals, in the men’s restroom, are located too high.		4.18		At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. Modify one urinal so that the rim is no higher than 17-inches.		L	H	M	6 5	\$100	See the Accessible Urinals figure for more details.			
64. Sixth Floor - Restrooms		The seat cover dispenser, in the Women’s restroom, is located too high at 66-inches.		4.2.5 4.2.6 4.24		At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. Lower at least one seat cover dispenser in each restroom to meet ADAAG reach range specifications.		H	H	M	6 8	\$100	See Building Block #10 – Reach Ranges #1, #2, #3.			
65. Seventh Floor		The counter, in the Engineering Department, is located too high at 42-inches.		7.2(2)		At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.		H	H	M	1 0 7	\$0	ADAAG  New ADAAG			
66. Seventh Floor		Round door hardware exists on the entrance door to the conference room in the Engineering Department.		4.13		According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.		L	H	M	1 0 5	\$25	See Attachment B – Accessible Door Hardware for information on inexpensive add-on lever handles.			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
67. Seventh Floor	The public counter, in the Central Inspection Department, is located too high at 48-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	109	\$0	<a href="#">ADAAG</a> <a href="#">New ADAAG</a>			
68. Seventh Floor	The public counters, in the Zoning Plans Examination room of the Housing Department, are located too high at 48-inches and 40-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	11112	\$0	<a href="#">ADAAG</a> <a href="#">New ADAAG</a>			
69. Seventh Floor	The faucet hardware, on the existing drinking fountain, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b>	L	L	M	113	\$150	<a href="#">ADAAG</a> <a href="#">Building Block 7 – Drinking Fountains</a>			
70. Floor Eight	The public counter, in the Public Works Department, is located too high at 40-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	84	\$0	<a href="#">ADAAG</a> <a href="#">New ADAAG</a>			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations	Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
71. Floor Eight	Round door hardware exists on the entrance doors of rooms and spaces throughout the Public Works Department.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.</b>	L	H	M	<a href="#">85</a>	\$300	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
72. Floor Eight	The accessible path of travel is too narrow, on the interior of the Public Works Department, due to the placement of a recycling bin. .	<a href="#">4.3.3</a>	According to ADAAG, the minimum clear width of an accessible route shall be 36 in (915 mm) except at doors (see <a href="#">4.13.5</a> and <a href="#">4.13.6</a> ), and other points not exceeding 24-inches in length. Move the recycling bin or otherwise ensure the path of travel meets ADAAG specifications.	M	H	M	<a href="#">86</a>	\$0	<a href="#">ADAAG</a>			
73. Floor Eight	The counter, in the Engineering Department, is located too high at 40-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	N A	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			
74. Floor Eight	Round door hardware exists on the entrance door of Conference Room N.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.</b>	M	H	M	<a href="#">88</a>	\$100	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
75. Floor Eight	Round door hardware exists on the entrance door of the Building Services Department.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.</b>	H	H	M	91	\$200	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
76. Floor Eight	The public counter, in the Building Services Department, is located too high at 40-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>	H	H	M	90	\$0	<a href="#">ADAAG</a> <a href="#">New ADAAG</a>			
77. Floor Eight	The faucet hardware, on the existing drinking fountain, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b>	L	L	M	92	\$150	<a href="#">ADAAG</a> <a href="#">Building Block 7 – Drinking Fountains</a>			
78. Floor Eight - Restrooms	The accessible toilet stalls, in the men's and women's restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall, lack of rear grab bars, toilets not centered at 18-inches, toilet seats too high at 20-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every restroom may not need to be made fully accessible, so long as restrooms services, as a whole, are accessible and usable by patrons with disabilities. Therefore, this restroom may not need to be made fully accessible so long as other fully accessible restrooms are fully accessible and in close proximity to inaccessible restrooms.	M	H	M	66 68	\$5,000	<a href="#">Restroom Figures – Building Blocks</a>			



**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
79. Floor Eight - Restrooms	Appropriate maneuvering clearance does not exist at the entrance doors leading to the men's and women's restrooms.	<a href="#">4.13.6</a>	The existing entrance doors provide 4-inches of space at the latch pull side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify these doors to comply with ADAAG specifications.</b>	M	H	M	93100	\$1,000	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			
80. Floor Eight - Restrooms	The seat cover dispensers, in the men's and Women's restrooms, are located too high at 66-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser in each restroom to meet ADAAG reach range specifications.</b>	H	H	M	96101	\$100	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3.</a>			
81. Floor Eight - Restrooms	Urinals, in the men's restroom, are located too high at 23-inches	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 23-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	84	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
82. Floor Eight - Restrooms	The coat hooks, in the men's, restroom, is located too high at 66-inches.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>	L	H	M	95	\$20	<a href="#">Building Block 10 – Reach Ranges</a>			
83. Ninth Floor	A hi-lo drinking fountain does not exist on this level	<a href="#">4.15</a> <a href="#">4.1.3(10(a))</a>	According to ADAAG if only one drinking fountain is provided on a floor there shall be a drinking fountain which is accessible to individuals who use wheelchairs and one accessible to those who have difficulty bending or stooping. <b>Ensure that at least one set of hi-lo drinking fountains exist on this floor.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every feature of a facility may not need to be made fully accessible, so long as this feature, as a whole, is accessible and usable by patrons with disabilities. Therefore, drinking fountains on this floor may not need to be made fully accessible so long as other fully accessible drinking fountains are fully accessible and in close proximity to inaccessible drinking fountains.	L	L	M		\$0	<a href="#">Building Block 7 – Drinking Fountains</a>			



[illegible]

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
88. Ninth Floor - Restrooms	Urinals, in the men's restroom, are located too high at 24-inches	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	7 2	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
89. Ninth Floor - Restrooms	In the men's and women's restrooms, the paper towel dispensers are not within reach range.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Ensure at least one paper towel dispenser; in each restroom, is within ADAAG specified reach ranges.</b>	M	H	M	7 4 7 9	\$50	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3.</a>			
90. Ninth Floor - Restrooms	The seat cover dispenser, in the Women's restroom, is located too high at 60-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser in each restroom to meet ADAAG reach range specifications.</b>	H	H	M	7 7	\$100	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3.</a>			
91. Tenth Floor	Round door hardware exists on the entrance door of the Metro Area Planning Department.	<a href="#">4.13</a>	According to ADAAG, any doors used by the general public in existing buildings are required to have opening hardware, which does not require tight grasping or twisting of the wrist to operate. <b>Modify all doors used by the public by replacing doorknobs with lever-type hardware or installing add-on levers.</b>	H	H	M	5 0 5 1	\$200	See Attachment B – <a href="#">Accessible Door Hardware</a> for information on inexpensive add-on lever handles.			
92. Tenth Floor	The public counter, in the Map Room, is located too high at 42-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or an accessible lowered counter or desk should exist in close proximity to the counter. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary.</b>	H	H	M	5 2	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>			

[illegible]

[illegible]

[illegible]

[illegible]



**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access		Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction		Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)	
108. Eleventh Floor - Restrooms	Urinals, in the men’s restroom, are located too high at 24-inches	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>		L	H	M	N A	\$250	See <a href="#">the Accessible Urinals</a> figure for more details.				
109. Eleventh Floor - Restrooms	Appropriate clear floor space does not exist at the baby changing station in the women’s restroom.	<a href="#">4.2.4</a>	The minimum clear floor or ground space required to accommodate a single, stationary wheelchair and occupant is 30 in by 48 in (760 mm by 1220 mm) (see <a href="#">Fig. 4(a)</a> ). The minimum clear floor or ground space for wheelchairs may be positioned for forward or parallel approach to an object (see <a href="#">Fig. 4(b)</a> and <a href="#">(c)</a> ). Clear floor or ground space for wheelchairs may be part of the knee space required under some objects. <b>Ensure that appropriate clear floor space exists at the baby changing station.</b>		M	H	M	4 7	\$300	ADAAG				
110. Floor Twelve	The public counter, in the Department of Finance, is located too high at 40-inches.	<a href="#">7.2(2)</a>	At counters where goods and services are distributed, but do not include cash registers, either a portion of the counter is required to be accessible or and accessible lowered counter or desk should exist in close proximity to the counter. Accessible counters are a maximum of 36-inches high and a minimum of 36-inches long. <b>Ensure that an accessible desk, in close proximity to the counter, is available and can be utilized when necessary regarding an individuals disability.</b>		H	H	M	3 4 3 5	\$0	<a href="#">ADAAG</a>  <a href="#">New ADAAG</a>				
111. Floor Twelve	The faucet hardware, on the existing drinking fountains, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every feature of a facility may not need to be made fully accessible, so long as this feature, as a whole, is accessible and usable by patrons with disabilities. Therefore, drinking fountains on this floor may not need to be made fully accessible so long as other fully accessible drinking fountains are fully accessible and in close proximity to inaccessible drinking fountains.		L	H	M	3 2	\$150	ADAAG  <a href="#">Building Block 7 – Drinking Fountains</a>				



**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
111. Floor Twelve - Restrooms	The accessible toilet stalls, in the men's and women's restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall, lack of rear grab bars or short rear grab bars or not properly located, toilets not centered at 18-inches, toilet seats too high at 20-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every restroom may not need to be made fully accessible, so long as restrooms services, as a whole, are accessible and usable by patrons with disabilities. Therefore, this restroom may not need to be made fully accessible so long as other fully accessible restrooms are in close proximity to inaccessible restrooms.	M	H	M	2831	\$5,000	<a href="#">Restroom Figures – Building Blocks</a>			
112. Floor Twelve - Restrooms	Appropriate maneuvering clearance does not exist at the entrance doors to the Men's and women's restrooms.	<a href="#">4.13.6</a>	The existing entrance doors provide 2-inches of space at the latch pull side interior side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify these doors to comply with ADAAG specifications, or otherwise ensure that an appropriate maneuvering space exists.</b>	M	H	M	25	\$1,000	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			
113. Floor Twelve - Restrooms	The seat cover dispensers, in the Men's and Women's restrooms, are located too high at 64-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser in each restroom to meet ADAAG reach range specifications.</b>	H	H	M	30	\$200	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3.</a>			
114. Floor Twelve - Restrooms	Urinals, in the men's restroom, are located too high at 24-inches	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	26	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access		Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction		Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)	
115. Floor Twelve - Restrooms	The coat hooks, in the men’s and women’s, restroom, is located too high at 66-inches.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>		L	H	M	<a href="#">29</a>	\$20	<a href="#">Building Block 10 – Reach Ranges</a>				
116. Floor Twelve - Restrooms	Appropriate clear floor space does not exist at the baby changing station in the women’s restroom.	<a href="#">4.2.4</a>	The minimum clear floor or ground space required to accommodate a single, stationary wheelchair and occupant is 30 in by 48 in (760 mm by 1220 mm) (see <a href="#">Fig. 4(a)</a> ). The minimum clear floor or ground space for wheelchairs may be positioned for forward or parallel approach to an object (see <a href="#">Fig. 4(b)</a> and <a href="#">(c)</a> ). Clear floor or ground space for wheelchairs may be part of the knee space required under some objects. <b>Ensure that appropriate clear floor space exists at the baby changing station.</b>		M	H	M	<a href="#">47</a>	\$300	ADAAG				
117. Floor Thirteen	The faucet hardware, on the existing drinking fountains, requires a tight grasp and twisting of the wrist to operate.	<a href="#">4.27.4</a>	According to ADAAG, controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. <b>Ensure that the operating mechanisms on all drinking fountains, which are required to be accessible, meet ADAAG specifications.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every feature of a facility may not need to be made fully accessible, so long as this feature, as a whole, is accessible and usable by patrons with disabilities. Therefore, drinking fountains on this floor may not need to be made fully accessible so long as other fully accessible drinking fountains are fully accessible and in close proximity to inaccessible drinking fountains.		L	H	M	<a href="#">14</a>	\$150	ADAAG  <a href="#">Building Block 7 – Drinking Fountains</a>				
118. Floor Thirteen	The counter, in the City Clerk’s Office, is located too high measuring 40-inches.	<a href="#">7.2</a>	ADAAG requires a minimum 36-inch long portion of sales or service counters to be a maximum height of 36-inches. <b>Lower a portion of the existing counter to a maximum height of 36-inches.</b>		M	H	M	<a href="#">16</a>	\$200	ADAAG  <a href="#">New ADAAG</a>				

[illegible]

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies	Recommended Corrections/Modifications to Ensure Program Access	Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction	Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed (Include initial)
122. Floor Thirteen - Restrooms	The accessible toilet stalls, in the men's and women's restrooms, are totally inaccessible due to numerous barriers.	<a href="#">4.23</a>	Inconsistencies include, but are not limited to, very narrow stall, lack of rear grab bars or short rear grab bars or not properly located, toilets not centered at 18-inches, toilet seats too high at 20-inches, etc. <b>Modify the restrooms to comply with ADAAG specifications, if it is technically feasible to do so.</b> Note: It should be understood that, according to the program access provisions of Title II – pertaining to existing buildings, each and every restroom may not need to be made fully accessible, so long as restrooms services, as a whole, are accessible and usable by patrons with disabilities. Therefore, this restroom may not need to be made fully accessible so long as other fully accessible restrooms are in close proximity to inaccessible restrooms.	M	H	M	5 6 1 0 1 1	\$5,000	<a href="#">Restroom Figures – Building Blocks</a>			
123. Floor Thirteen - Restrooms	The seat cover dispensers, in the Men's and Women's restrooms, are located too high at 64-inches.	<a href="#">4.2.5</a> <a href="#">4.2.6</a> <a href="#">4.24</a>	At least one of each type of dispenser is required to be accessible and must be within a maximum reach range of 54-inches where a side reach is possible and a maximum of 48-inches where only a forward reach is possible, to the highest operable part. <b>Lower at least one seat cover dispenser in each restroom to meet ADAAG reach range specifications.</b>	H	H	M	2	\$200	See <a href="#">Building Block #10 – Reach Ranges #1, #2, #3.</a>			
124. Floor Thirteen - Restrooms	Urinals, in the men's restroom, are located too high at 24-inches	<a href="#">4.18</a>	At least one urinal is required to be located so that the rim is a maximum of 17-inches high. Existing urinals have rims located at 24-inches high. <b>Modify one urinal so that the rim is no higher than 17-inches.</b>	L	H	M	3	\$100	See <a href="#">the Accessible Urinals</a> figure for more details.			
125. Floor Thirteen - Restrooms	Appropriate maneuvering clearance does not exist at the entrance doors to the Men's and women's restrooms.	<a href="#">4.13.6</a>	The existing entrance doors provide 2-inches of space at the latch pull side interior side. ADAAG requires at least 18-inches to the latch pull side of doors of this type. <b>Modify these doors to comply with ADAAG specifications, or otherwise ensure that an appropriate maneuvering space exists.</b>	M	H	M	4	\$1,000	See <a href="#">Building Block 8 – Accessible Doors</a> for more information regarding maneuvering space			

**City of Wichita – ADA/504 Transition Plan – City Hall - August 2005** Legend: **Blue** font identifies hyperlinked documents – **Red** font indicates recommended changes to structures or policies

Locations		Structural Inconsistencies		Recommended Corrections/Modifications to Ensure Program Access		Criteria – L=low, M=medium, H=high			Supplemental Technical Information			Finalized Actions		
Location	Identified Issue	ADAAG Specifications	Recommended Correction		Priority (overall)	Public Access	Frequency - PWD	Photo #	Conceptual Costs	Support Information	Finalized Correction	Date to be Corrected	Date Completed <i>(Include initial)</i>	
126. Floor Thirteen - Restrooms	The coat hooks, in the women’s, restroom, is located too high at 66-inches.	<a href="#">4.25.3</a>	Where coat racks or hooks are provided, at least one must comply with reach ranges defined by ADAAG <a href="#">4.2.5</a> or <a href="#">4.2.6</a> . <b>Install lowered coat hooks in each restroom making sure not to make the hooks protruding objects.</b>		L	H	M	10	\$20	<a href="#">Building Block 10 – Reach Ranges</a>				
127. Floor Thirteen - Restrooms	Appropriate clear floor space does not exist at the baby changing station in the women’s restroom.	<a href="#">4.2.4</a>	The minimum clear floor or ground space required to accommodate a single, stationary wheelchair and occupant is 30 in by 48 in (760 mm by 1220 mm) (see <a href="#">Fig. 4(a)</a> ). The minimum clear floor or ground space for wheelchairs may be positioned for forward or parallel approach to an object (see <a href="#">Fig. 4(b)</a> and <a href="#">(c)</a> ). Clear floor or ground space for wheelchairs may be part of the knee space required under some objects. <b>Ensure that appropriate clear floor space exists at the baby changing station.</b>		M	H	M	9	\$300	ADAAG				

**City Hall - Conceptual Cost Projections**

<b>Total</b>	<b>\$87,375</b>
<b>Year One (Very High)</b>	<b>\$3,000</b>
<b>Year Three (High)</b>	<b>\$21,845</b>
<b>Year Five (Medium)</b>	<b>\$56,200</b>
<b>Year Ten (Low)</b>	<b>\$7,330</b>